

METCON-1 910907-1.02

Copyright (c) 1991 T.A.P.R. All Rights Reserved.

Checksum: 0x6FBB

=amap

-A- MEMORY DISPLAY

```

P6      P5      P4      P2      P0
0000 0000  0000 0000  0000 0000  0000 0000  0000 0000  OUT (08 07
06 05 04)
0000 0000  0000 0000  0000 0000  0000 0000  0011 1111  IN  (0D 0C 0B
0A 09)
0000 0000  0000 0000  0000 0000  0000 0000  0011 1111  CHG (12 11
10 0F 0E)
```

```

7  6  5  4  3  2  1  0
00000 00000 00000 00000 00000 00000 00000 00000  F/P CTRS
(21/22-13/14)
```

```

7  6  5  4  3  2  1  0
255 255 255 255 255 255 255 255  ADC (2A-23)
```

-A- MEMORY DISPLAY COMPLETE

=ary09

-A- 09-063 3F 0011 1111

=ary9

-A- ??? ADDRESS ERROR ???

=ary09

-A- 09-062 3E 0011 1110

=ary09

-A- 09-061 3D 0011 1101

=ary09

-A- 09-059 3B 0011 1011

=ary09

-A- 09-055 37 0011 0111

=ary09

-A- 09-047 2F 0010 1111

=ary09
-A- 09-031 1F 0001 1111
=ary09
-A- 09-063 3F 0011 1111
=aewrite
-A- EEPROM WRITE/READ OK
=ary09
-A- 09-063 3F 0011 1111
=ary05
-A- 05-000 00 0000 0000
=awy053f
-A- 05-063 3F 0011 1111
=ary05
-A- 05-063 3F 0011 1111
=ary09
-A- 09-000 00 0000 0000
=ary0501
-A- 05-063 3F 0011 1111
=awy0501
-A- 05-001 01 0000 0001
=ary09
-A- 09-062 3E 0011 1110
=awy0502
-A- 05-002 02 0000 0010
=ary09
-A- 09-061 3D 0011 1101
=awy0504
-A- 05-004 04 0000 0100
=ary09
-A- 09-059 3B 0011 1011
=awy0508
-A- 05-008 08 0000 1000
=ary09
-A- 09-055 37 0011 0111
=awy0510
-A- 05-016 10 0001 0000
=ary09
-A- 09-055 37 0011 0111
=ary09
-A- 09-047 2F 0010 1111

=awy0520

-A- 05-032 20 0010 0000

=ary09

-A- 09-031 1F 0001 1111

=awy05c0

-A- 05-192 C0 1100 0000

=ary09

-A- 09-063 3F 0011 1111